



**SW Test Workshop**  
Semiconductor Wafer Test Workshop

# REDUCING PROBE NEEDLE DAMAGE ON BOND PAD USING SIX SIGMA METHODOLOGY



**Glenn T. Placido**  
Principal Engineer

June 5-8, 2016

# Agenda

- The DMAIC Model
- What is probe damage?
- The Define phase
- MSA – Measurement of System Analysis
- Analyze Phase – Identification and validation of KPIVs
- Improve Phase
- Control –Standardization of corrective action
- Revisiting probe damage
- Conclusion / Recommendation



# SIX SIGMA

## The DMAIC Model




Define Opportunity  
(What is important?)

**Define** the goals of the improvement activity.

Select the appropriate responses (Y's) to be improved.

SW Test Workshop - June 5-8, 2016

“ Another wafer for scrap due to probe damage. We don't have enough wafers to support delivery”.



“We need to explain to the customer why we are delayed”

# VOICE OF THE CUSTOMERS

“What probe damage again!!! Another wafer for 100% inspection!!!”. When will this end? Huhuhu






# What is Probe Damage?



- Probe damage is defect induced during wafer probing which exposes the base metal or touches the pad perimeter / seal ring of the bond pad.

GOOD




Criteria – Accept any visible gap or the operator can clearly see that there was no damage on seal ring of the bond pad vs. probe mark (including aluminum push-outs).

REJECTS






Criteria – Reject if probemark touches the seal ring of the bond pad area




## b.) Exposed Oxide on Bonding Pad

CRITERIA: Reject probe marks that exposes oxide beneath the bond pad metal

REJECTS




# Why Is Probe Damage a Problem?






# Why Is Probe Damage a Problem?

## Trend Chart of Probe Damage



# Why Is Probe Damage a Problem?

## Trend Chart of MRB Occurrence





## Define

- Project Selection
- Project Description
- Project Charter
- Project Impact
- Define Phase Summary

Measure


Analyze

Improve

Control



# Project Charter - Team Composition



SW Test Workshop - June 5-8, 2016

## Define

- Project Selection
- Project Description
- Project Charter
- Project Impact
- Define Phase Summary

Measure

Analyze

Improve

Control



## Business Case

- Probe damage is the number 1 visual defect contributor at wafer sort. Yield and cycle time is affected due to this problem.

## Problem Statement

- Probe damage is a consistent top defect at wafer sort with an average ppm of 578. the number 1 visual defect contributor at wafer sort. Yield and cycle time is affected due to this problem. There is also an average of 16MRB per month.

## Project Metrics

- Probe damage PPM
- Number of MRB occurrence

## Goal Statement

- Reduce probe damage PPM by 50% from 578 to 289
- To reduce MRB occurrence by 75% due to probe damage from an average of 16 per month to 4 wafers per month.

SW Test Workshop - June 5-8, 2016



Define

# Macro Map (SIPOC)


- Project Selection
- Project Description
- Project Charter
- Project Impact
- Define Phase Summary


Measure

Analyze

Improve

Control

Supplier	Input	Process	Output	Customer
Wafer fab	Unsorted Wafers	<b>Wafer Probing</b> 	Sorted wafers	Assembly
Probe Card Maintenance	Probe Card		Customers	
Probe card build	Probe Needle			
Equipment Maintenance	Prober			



Process steps highlighted are the focus of this project

## SW Test Workshop - June 5-8, 2016

# SIX SIGMA

## The DMAIC Model



Define Opportunity  
*(What is important?)*



Measure Performance  
*(How are we doing?)*



**Define** the goals of the improvement activity.

Select the appropriate responses (Y's) to be improved.

**Measure** the existing system.

Gather data to measure and verify the response variable --- the problem or improvement opportunity.

SW Test Workshop - June 5-8, 2016



# Measure

- **Measurement Systems Analysis**
  - Final outgoing inspection (FOI), consistency and effectiveness as well as its miss rate and false alarm rate were checked.

Define Measure Analyze Improve Control



SW Test Workshop - June 5-8, 2016

Define

Measure

- Macro Map (SIPOC)
- KPOV Characteristics
- Measurement Systems Analysis
- Capability Analysis
- Measure Phase Summary

Analyze

Improve

Control



## Summary of Attribute MSA Study

KPOV (Output or Response Variable)	MSA Method	Criteria	Actual Result	Remark/s
Probe Damage	Consistency	$\geq 90\%$	# 1 = 96.61% # 2= 96.61%	Pass
	Effectiveness (Individual)	$\geq 90\%$	#1= 98.15% #3= 98.31%	Pass
		$\leq 2\%$	94.92%	Pass
		$\leq 2\%$	# 1 = 1.89% # 2= 0.38% #3= 1.52%	Pass
	False Alarm Rate	$\leq 5\%$	# 1 = 0.0% # 2=0.0% #3= 0.0%	Pass

PASS !!!

### Interpretation:

- Consistency and Effectiveness passed the Attributes MSA criteria.
  - All three operators were able to detect probe damage.

SW Test Workshop - June 5-8, 2016

# SIX SIGMA

## The DMAIC Model



**Define**

Define Opportunity  
*(What is important?)*




**Measure**

Measure Performance  
*(How are we doing?)*



**Analyze**

Analyze Opportunity  
*(What is wrong?)*



**Improve**



**Control**

**Define** the goals of the improvement activity.

Select the appropriate responses (Y's) to be improved.

**Measure** the existing system.

Gather data to measure and verify the response variable --- the problem or improvement opportunity.

**Analyze** the system to identify the causes or gaps.

Find the relevant X's.



# Analyze

- Identification of KPIVs
  - Based on the process mapping and fishbone diagram, the team identified 144 KPIVs that will contribute on Probe Damage.
  - The team decided to select and prioritize 78 KPIVs out of 144 identified KPIVs. The selection and prioritization was based on the impact to Probe Damage. After combining similar KPIVs, the team came up with 15 validation plans.
- Validation of KPIVs
  - After thorough validation and hypothesis testing conducted all 15 KPIVs are identified to be valid.
  - Therefore, the significant and valid KPIVs are now to be addressed in Improve Phase.

Define Measure Analyze Improve Control



SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze


- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control



# Detailed Process Map



SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control



# SIPOC

Supplier	Input	Process	Output	Customer
<ul style="list-style-type: none"> <li>o ProbeCard Build</li> <li>o Prober Maintenance</li> <li>o FAB</li> <li>o Loadboard Maintenance</li> <li>o ITS</li> <li>o Prober Maintenance</li> <li>o Operation</li> <li>o KLA</li> </ul>	<ul style="list-style-type: none"> <li>o ProbeCard</li> <li>o Prober</li> <li>o Wafer</li> <li>o Loadboard</li> <li>o Cleaning material</li> <li>o Cleaning material replacement procedure</li> <li>o Operator</li> <li>o Cleaning Frequency</li> </ul>	<p>16</p> <div style="border: 1px solid black; background-color: #f8d7da; padding: 5px; text-align: center;">Needle cleaning (KLA define)</div>	Probecard needle free of debris	Production
		<p>17</p> <div style="border: 1px solid black; background-color: #d4edda; padding: 5px; text-align: center;">Operator Inspection (start of the shift; change of peripherals; every 1<sup>st</sup>, 6<sup>th</sup> wafer)</div>		
		<p>18</p> <div style="border: 1px solid black; background-color: #d4edda; padding: 5px; text-align: center;">Auto probe mark inspection</div>		
<ul style="list-style-type: none"> <li>o ProbeCard Build</li> <li>o Prober Maintenance</li> <li>o FAB</li> <li>o Loadboard Maintenance</li> <li>o Operation</li> <li>o Operation</li> <li>o Prober Maintenance</li> </ul>	<ul style="list-style-type: none"> <li>o ProbeCard</li> <li>o Prober</li> <li>o Wafer</li> <li>o Loadboard</li> <li>o Inspection method</li> <li>o Operator</li> <li>o Maintenance troubleshooting guide during isolation and endorsement to production</li> </ul>	<p>13</p> <div style="border: 1px solid black; background-color: #f8d7da; padding: 5px; text-align: center;">Perform Isolation</div>	Gross rejection/equipment problem resolved.	Production

## SW Test Workshop - June 5-8, 2016



Define

Measure

Analyze


- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control



# Cause and Effect Analysis



## SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control



# Validation Plan for Shortlisted KPIVs



Microsoft Office  
Excel 97-2003 Worksheet

## C&E Matrix

C&E Matrix (Selected)

No.	Process Step	Input	KPIV No.	Physical condition	Visualy good	9					90	7	Selected	
1	Relocate Prober	Prober	1										ected	
		Maintenance	3											ected
2	Install Probecard and Loadboard	Prober	4										ected	
		Probecard	6										ected	
		Loadboard	8										ected	
		Maintenance	12											ected
3	Dock Test Head	Prober	13										ected	
		Probecard	15	Physical condition	Visualy good	9						90	7	Selected
		Maintenance	21	Skills in test head docking	no specs....	9						90	8	Selected
4	Load KLA/BOP	Prober										90	9	Selected
		Probecard										90	10	Selected
		Maintenance										90	11	Selected
6	Soak Probecard	Prober										90	12	Selected
		Probecard										90	13	Selected
		Operator										90	14	Selected
		Maintenance	44	BOP DISK	updated with label (device		9						90	15
		Standard Wafer	45	Condition of standard wafer	Standard wafer replenishment procedure.	9						90	16	Selected
7	Set z-ht and overdrive											90	17	Selected
												90	18	Selected
												90	19	Selected
		Probecard	48	Physical condition	length	Visualy good - Probemark is acceptable as per criteria.	9						90	20

Identified **144** KPIVs after thorough process mapping and root cause analysis

Shortlisted **78** of **144** KPIVs after prioritization

15 Validation Plans

# Validation Plan for Shortlisted KPIVs

Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control



KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
1	Equipment (Prober)	Operational Condition of prober.	Prober XY shift will increase if prober was relocated.	Validate if XY shift will increase after prober movement.
2	Equipment (Prober)	Operational Condition of prober.	Using a defective prober footings will cause planarity problem and can induce probe damage.	Validate effect of a defective footings on probemark
3	Equipment (Prober)	Operational Condition of prober.	Card relative Z-ht and overdrive does not have effect on the probemark size.	To validate effective card relative Z-ht; and overdrive which can induce minimum probemark
4	Equipment (Prober)	Operational Condition of prober.	"Model not found" and "auto focus error" will induce probedamage if not properly corrected.	Validate effect of the ff errors, model not found, and auto focus error on the probemark.
5	Equipment (Prober)	Operational Condition of prober.	Incorrect soak time will have effect on probemark size	Validate effect of soaking on the probemark (10min auto-soak)
6	Operator	Soaking procedure.	Incorrect soak time will have effect on probemark size	Validate effect of manual soaking on the probemark (10min- PC-PREHEAT 2 HRS PROBER SOAK FOR INITIAL SETUP)
7	Method	Inspection procedure and equipment repair	Procedures is not yet robust or is not yet define during : <ul style="list-style-type: none"> <li>* Prober relocaton</li> <li>* PC/LB installation</li> <li>* test head docking</li> <li>* Standard wafer replenishment</li> <li>* settings, head overdrive</li> </ul>	Validate specs if being followed in actual : <ul style="list-style-type: none"> <li>* Prober relocaton checklist/guide prior endorsement to production</li> <li>* PC/LB installation</li> <li>* test head docking</li> <li>* Standard wafer replenishment procedure</li> </ul>
8	Probe Csrld	In good condition	Using out of spec screws in PC stifener (ELTESO PC) can induce probe damage.	Validate Effect of using out of screws can induce probe damage..
9	BOP Disk	Updated and with label	Loading an wrong/not updated BOP disk can cause probe damage	Validate effect of using a wrong / not updated BOP disk
10	Prober	Operational Condition of prober.	Uncalibrated cleaning unit height can smash the probecard and eventually leads to probe damage.	Effect of using uncalibrated cleaning unit height
11	Cleaning material	Lapping paper	Replacing the cleaning material incorrectly will have bubbles and eventually mis-aligning the needle during needle cleaning.	Effect of wrong replacement if cleaning material
12	Cleaning material	Lapping paper	Accumulation of debris on the probe needle can cause probe damage.	Effect of debris on the probe needle.
13	Cleaning material	Lapping paper	Worn out cleaning material will not be able to sufficiently clean the probecard needle and eventually causes probe damage.	Effect of using worn out cleaning material
14	Method	Probe oprating procedure	Leaning on the test head and removal of cable on cable setup will induce probe damage.	Effect of leaning on the teast head and removal of cable while ongoing test.
15	Probecard	Visually good; planarity at +/- 0.3mils	Probecard with planarity issue can cause probe damage.	Validate effect of using probecard with planarity issue.

15 Validation Plans



# Validation Plan for Shortlisted KPIVs

Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control



KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan	Validation Result
1	Equipment (Prober)	Operational Condition of prober.	Prober XY shift will increase if prober was relocated.	Validate if XY shift will increase after prober movement.	VALID
2	Equipment (Prober)	Operational Condition of prober.	Using a defective prober footings will cause planarity problem and can induce probe damage.	Validate effect of a defective footings on probemark	VALID
3	Equipment (Prober)	Operational Condition of prober.	Card relative Z-ht and overdrive does not have effect on the probemark size.	To validate effective card relative Z-ht; and overdrive which can induce minimum probemark	VALID
4	Equipment (Prober)	Operational Condition of prober.	"Model not found" and "auto focus error" will induce probedamage if not properly corrected.	Validate effect of the ff errors, model not found, and auto focus error on the probemark.	VALID
5	Equipment (Prober)	Operational Condition of prober.	Incorrect soak time will have effect on probemark size	Validate effect of soaking on the probemark (10min auto-soak)	VALID
6	Operator	Soaking procedure.	Incorrect soak time will have effect on probemark size	Validate effect of manual soaking on the probemark (10min- PC- PREHEAT 2 HRS PROBER SOAK FOR INITIAL SETUP)	VALID
7	Method	Inspection procedure and equipment repair	Procedures is not yet robust or is not yet define during : * Prober relocaton * PC/LB installation * test head docking * Standard wafer replenishment * setting head overdrive	Validate specs if being followed in actual : * Prober relocaton checklist/guide prior endorsement to production * PC/LB installation * test head docking * Standard wafer replenishment procedure. * documented procedure in setting head overdrive	VALID
			* Equipment isolation * Probemark inspection criteria * Inspection of probecard needle prior use	* Probemark inspection criteria * Inspection of probecard needle prior use	
8	Probe Csr	In good condition	Using out of spec screws in PC stifener (ELTESO PC) can induce probe damage.	Validate Effect of using out of screws can induce probe damage..	VALID
9	BOP Disk	Updated and with label	Loading an wrong/not updated BOP disk can cause probe damage	Validate effect of using a wrong / not updated BOP disk	VALID
10	Prober	Operational Condition of prober.	Uncalibrated cleaning unit height can smash the probecard and eventually leads to probe damage.	Effect of using uncalibrated cleaning unit height	VALID
11	Cleaning material	Lapping paper	Replacing the cleaning material incorrectly will have bubbles and eventually mis-aligning the needle during needle cleaning.	Effect of wrong replacement if cleaning material	VALID
12	Cleaning material	Lapping paper	Accumulation of debris on the probe needle can cause probe damage.	Effect of debris on the probe needle.	VALID
13	Cleaning material	Lapping paper	Worn out cleaning material will not be able to sufficiently clean the probecard needle and eventually causes probe damage.	Effect of using worn out cleaning material	VALID
14	Method	Probe oprating procedure	Leaning on the test head and removal of cable on cable setup will induce probe damage.	Effect of leaning on the teast head and removal of cable while ongoing test.	VALID
15	Probecard	Visually good; planarity at +/- 0.3mils	Probecard with planarity issue can cause probe damage.	Validate effect of using probecard with planarity issue.	VALID

15 Valid KPIVs

Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve


Control



# Validation Result for Operational Condition of Prober

KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
1	Wafer	Operational condition of prober	Prober XY shift will increase during equipment relocation	Using t-test validate increase on prober XY shift during prober relocation.

Objective: To verify if shift on prober XY will increase after prober relocation.



**Conclusion:** The above test results showed that during the first relocation, there is no significant difference in the X and Y probe mark shifts. In the succeeding two relocations, there was no significant shift in the Y axis still, BUT for the X axis the shift now became very significant Therefore the identified KPIV is **VALID**.

Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve


Control



# Validation Result for Operational Condition of Prober

KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
2	Wafer	Operational condition of prober	Using defective prober footings will cause planarity problem and can induce probe damage.	Using t-test validate planarity using good vs defective prober footing.

Objective: To verify if using a defective prober footing can cause probe damage..



**Conclusion:** Result shows that there is a significant difference in the X and Y shifts when using good footings vs defective footings. Therefore the identified KPIV is *VALID*.



Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control



## Validation Result for Operational Condition of Prober

KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
3	Wafer	Operational condition of prober	Card relative Z ht and overdrive does not affect probemark size.	Using DOE to check effect on probe mark size of different z ht and overdrive setting

Objective: To verify effect of card relative z ht and overdrive on probe mark size.




Photo at left show is the result of simulation in which the probe mark length (samples in red box) is much bigger and longer compared to a normal probe mark size.

**Conclusion:** Setting of card relative z height is critical as this will dictate the needle cleaning height, As Z height increases needle cleaning height also increases. This will cause probe card to smash and eventually probe damage will occur. Therefore the identified KPIV is *VALID*.

SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control



## Validation Result for Operational Condition of Prober

KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
4	Wafer	Operational condition of prober	"Model not found" and "auto focus error" will induce probe damage if not properly corrected.	Validate effect of the ff errors, model not found, and auto focus error on the probemark.

Objective: To verify if "Model not found" and "auto focus error" will induce probe damage if not properly corrected.

**Conclusion:** Although "Model not found" error was not replicated during the validation, the team still consider this as valid since "Model not found" error is due to probe card vs prober theta alignment and corrective action to address will be define. Therefore the identified KPIV is *VALID*.

SW Test Workshop - June 5-8, 2016



Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control



# Validation Result for Soaking Procedure

KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
5, 6	Operator	Soaking Procedure	Incorrect soak time will have effect on probemark size	Using DOE validate effect of soaking on the probemark (10min- PC- PREHEAT 2 HRS PROBER SOAK FOR INITIAL SETUP)

Objective: To verify if effect of soaking (prober soak – 2hrs; PC soak- 10min) on probe mark size and position.

Pattern	Probe Card pre heat (min)	Soak time (hrs)	Probe Mark Size
1	11	0	1
2	11	0	1
3	11	0	1
4	11	0	1
5	31	10	1
6	31	10	1
7	31	10	1
8	31	10	1
9	41	15	1
10	41	15	1
11	41	15	1
12	41	15	1
13	21	5	1
14	21	5	1
15	21	5	1
16	21	5	1
17	13	0	2
18	13	0	2
19	13	0	2
20	13	0	2
21	33	10	2
22	33	10	2
23	33	10	2
24	33	10	2
25	43	15	2
26	43	15	2
27	43	15	2
28	43	15	2
29	23	5	2
30	23	5	2
31	23	5	2
32	23	5	2
33	12	0	0
34	12	0	0
35	12	0	0
36	12	0	0
37	32	10	0
38	32	10	0
39	32	10	0
40	32	10	0

Device	0HSBA					
Temp	155°C					
Probing duration	2hours					
test time	30sec					
	X (µm)		Y (µm)			
Prober shift	2		2			
0 prober soak/ 10mins PC soak	First Die 1	First Die 2	Offset (less prober shift)	Last Die 1	Last Die 2	Offset (less prober shift)
X	6.2	20.3	-12.1	6.2	24.2	-16
Y	9.9	15.7	-3.8	9.9	15.1	-3.2
	X (µm)		Y (µm)			
Prober shift	4		2			
2 prober soak/ 5mins PC soak	First Die 1	First Die 2	Offset (less prober shift)	Last Die 1	Last Die 2	Offset (less prober shift)
X	54.5	36.5	14	56.5	37.1	15.4
Y	33.1	31.4	-0.3	29.6	34.9	-3.3

**Conclusion:** Result shows that prober soak and PC soaking is required as this affects the probe mark size and position which can lead to probe damage. Probe mark size and position will increase as PC soak time increases. Therefore the identified KPIV is *VALID*.



Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control



## Validation Result for Inspection Procedure and Equipment Setup/ Repair

KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
7	Method	Inspection procedure and equipment repair	Procedures is not yet robust or is not yet define	Check specs if procedure are existing.

Objective: To verify if there is an existing procedure define during :

- Prober relocation – No procedure
- PC/LB installation - No procedure
- Test head docking – No procedure
- Setting z-ht and overdrive – With procedure.
- Inspection methodology to detect theta alignment problem. No procedure.
- Inspection methodology –With procedure but needs to be enhanced.
- Theta alignment problem. – With procedure but needs to be enhanced.
- Detect prober XY shift problem – With procedure but needs to be enhanced.
- Correct prober XY shift problem – With procedure but needs to be enhanced.
- Methodology after equipment repair – With procedure but needs to be enhanced.
- Probemark inspection criteria – With procedure but needs to be enhanced.
- Inspection of probecard needle prior use – With Procedure.
- Different criteria at probe card build vs production - No procedure.

**Conclusion:** There are no procedures define on some of the critical activities above. For those identified with procedures, further enhancement needs to be done to increase detection of the problem. Each operator/technicians have their own procedures based on their experiences thus can result to poor detection of probe damage. Therefore the identified KPIV is *VALID*.

SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control




# Validation Result for Probe Card PC Stiffener Screws




KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
8	Method	Probe card in good condition.	Using out of spec screws in PC stifener (ELTESO PC) can induce probe damage.	Validate Effect of using out of screws can induce probe damage..

Objective: To verify if using out of spec screws in PC stiffener can cause probe damage.

Using PC with standard screws



Using PC with non standard screw



**Conclusion:** The PCB is not mounted floating on the stiffener. The root cause of this is the fact that not the special ELTESO screws are used to mount the PCB, standard screws (see picture ELTESO screws. Left is the correct screw, right is the out of spec screw). As a result the PCB is not floating and the expansion due to the temperature is driving the needle movement. Therefore the identified KPIV is *VALID*.



Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control




## Validation Result for Updated and Labelled BOP Disk

KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
9	BOP Disk	Updated and with label	Loading of wrong/not updated BOP disk can cause smash the probecard and eventually causes probe damage	Validate effect of using a wrong / not updated BOP disk

Objective: To verify if using wrong/not updated BOP disk can cause smash probecard and eventually causes probe damage.

### Inspection result after simulation



**Conclusion:** Incorrectly loading a BOP disk causes smash probecard, however, during validation, probe damage was not induced. This however does not mean that this probe damage will not happen thus the KPIV is VALID.

SW Test Workshop - June 5-8, 2016



Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control




## Validation Result for Frequent Tweaking of needle

KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
10	Probe Card	Probe card in good condition	Use of Sodium Hydroxide can cause weakening of probe needle which can lead to needle misalignment and eventually probe damage..	Check historical data .

Objective: Check historical data of probe card using sodium hydroxide and duralco epoxy.

0WICA PC with SN 081998 uses NAOH and Duralco and encountered misalign needle on the middle of the lot.



**Conclusion:** Sodium Hydroxide is the chemical used during needle etching. Application of this chemical is subjective and operator dependent while use of Duralco epoxy does not effectively hold the needle of the probecard. This eventually weakens the needle and will cause premature needle misalignment. The KPIV is therefore VALID.

SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve

Control



## Validation Result for Replacing of Lapping Paper

KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
11,12	Cleaning material	Updated and with label	Replacing the cleaning material incorrectly and worn out cleaning materials will eventually mis-align the needle during needle cleaning.	Validate effect of bubble during lapping paper replacement can cause probe damage.

Objective: To verify effect of wrong replacement of cleaning material and use of worn out cleaning material can induce probe damage.



Needle misalignment after needle cleaning using worn out needle cleaning material.

**Conclusion:** Replacing cleaning material without removing the original cleaning material will cause needle to smash due to additional 100um overdrive and consequently probe damage will occur. Using also an already worn out cleaning material will cause needle misalignment. The KPIV is therefore VALID.

SW Test Workshop - June 5-8, 2016



Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve


Control



## Validation Result for Accumulation of Debris on Lapping Paper

KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
13	Cleaning material	Lapping Paper	Accumulation of debris on the probe needle can cause probe damage.	Validate effect of accumulated debris on the probecard needle

Objective: To validate if accumulated debris on the probecard needle can induce probe damage.



**Conclusion:** Result shows that probe damage will occur if there is an accumulated dirt/debris on the probecard needle. The size and location of the probe damage coincides with that of the debris on the probecard needle. The KPIV therefore is VALID.

SW Test Workshop - June 5-8, 2016



Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve


Control



## Validation Result for Probe Operating Procedure

KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
14	Method	Probe operating procedure	Leaning on the test head and removal of cable on cable setup will induce probe damage.	Effect of leaning on the test head and removal of cable while ongoing test.

Objective: To verify if there is an effect on leaning on the test head and removal of cable while ongoing test will induce probe damage.



Before reseating of cable – No probe damage seen on the bond pad

After reseating of cable – Probe damage seen on the bond pad

**Conclusion:** Result shows that after reseating the cable, probe damage occurred. Therefore the identified KPIV is **VALID**.

SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze

- Identification of KPIVs
- Prioritization of KPIVs
- Validation Plan for KPIVs
- Results and Analysis:
  - Graphical, and/or
  - Statistical
- Analyze Phase Summary

Improve


Control



# Validation Result for Probe card Planarity

KPIV Plan No.	Input	Characteristic of Input (KPIV)	Hypothesis	Validation Plan
15	Probe card	Probe card planarity	<b>Probecard with planarity issue can cause probe damage.</b>	Validate effect of using probecard with planarity issue.


<b>Test Plan</b>	Chi-Squared Test
<b>Sample Size</b>	32 samples
<b>Hypothesis Statement</b>	$H_0$ : Probe damage (planar) = Probe damage (Non-planar) $H_a$ : Probe damage (planar) not = Probe damage (Non-planar)
<b>Test Result</b>	p-value < 0.0001
<b>Statistical Conclusion</b>	Reject $H_0$ @ 95% confidence level
<b>Practical Conclusion</b>	The occurrence of probedamage is significantly different between planar and non-planar probe card



## Summary of Result :

Probecard State	No Probe Damage	With Probe Damage
Non-Planar	0	16
Planar	16	0

Sample Photos



**Conclusion:** The result in the summary table is so convincing that even without the Chi-squared test one can confidently state that non-planar probe card is conclusively inducing probe damage. The KPIV therefore is VALID.

SW Test Workshop - June 5-8, 2016



# SIX SIGMA

## The DMAIC Model



Define Opportunity  
*(What is important?)*



Measure Performance  
*(How are we doing?)*



Analyze Opportunity  
*(What is wrong?)*



Improve Performance  
*(What needs to be done?)*



**Define** the goals of the improvement activity.

Select the appropriate responses (Y's) to be improved.

**Measure** the existing system.

Gather data to measure and verify the response variable --- the problem or improvement opportunity.

**Analyze** the system to identify the causes or gaps.

Find the relevant X's.

**Improve** the system.

Identify ways to eliminate the gap.

Reduce variability or eliminate the cause.



# Improve

## Corrective / Preventive Actions

- Implementation of a more robust and efficient set-up methodology to determine if there is an equipment or probe card issue prior running the complete lot shows early detection of issues.
  - Implementation of XY bracket during prober relocation also shows effective methodology when transporting one prober to another tester.
  - Use of POR screws on ELTESO probe card likewise eliminate probe damage caused by probe card expansion when subjected to high temp.
- Implementation Result
    - Significant improvement was observed after completion and partial implementation of a defined corrective actions.

Define Measure Analyze Improve Control



SW Test Workshop - June 5-8, 2016

# Corrective / Preventive Action (CAPA) Plan

Define

Measure

Analyze

Improve

Corrective / Preventive Action:

- DOE, and/or  
- Poka-Yoke

Implementation Result

Improve Phase Summary

Control



Item	Validated KPIV/Cause	Quick Win/s (Containment Action/s)	Permanent Action/s	Responsible/ Completion Date
1	<b>KPIV 1</b> Operational condition of prober after equipment relocation.	a. Enhance equipment buy-off prior MFG acceptance (production use).	1.1. Enhance equipment buy-off prior MFG acceptance (production use).  1.2. Use bracket during transfer of probers to support XY prober arm during relocation.	Six Sigma Team/ Done  Deployment (Maan L)/ Done  Rod Salmorin/ Done
2	<b>KPIV 2</b> Using defective prober footings will cause planarity problem and can induce probe damage.	a. Do one time checking of all prober footings.	1.1 Do one time checking of all prober footings.  1.2 Include checking of prober footings on the PM checklist	Bert Bugarin / Done  Rod Salmorin/Done
3	<b>KPIV 3</b> Incorrect card relative z height and over drive can cause probe damage	a. Enhance procedure during setting of card relative z height.	1.1 Enhance procedure during setting of card relative z height.	Glenn Placido/Done
4	<b>KPIV 4</b> "Model not found" and "auto focus error" will induce probe damage if not properly corrected.	a. Generate OCAP for this prober error.	1.1 Generate OCAP for this prober error.  1.2 Qualify PCB theta jig with tighter specs.	Glenn Placido / done.  Enan dela Cruz/ Done

SW Test Workshop - June 5-8, 2016



# Corrective / Preventive Action (CAPA) Plan

Define

Measure

Analyze

Improve

Corrective / Preventive Action:

- DOE, and/or  
- Poka-Yoke

Implementation Result

Improve Phase Summary

Control



Item	Validated KPIV/Cause	Quick Win/s (Containment Action/s)	Permanent Action/s	Responsible/ Completion Date
5	<b>KPIV 5,6</b> Incorrect soak time have effect on probe mark size and position.	a. Remove manual soaking by integrating soaking time on the prober to tester interface	1.1 Remove manual soaking by integrating soaking time on the prober to tester interface.	Sherwin Gan/Done.
6	<b>KPIV 7</b> Procedure is not yet robust/define	a. Generate specs for non existing procedures. b. Enhance existing procedure to improve detection of defects	1.1 Generate specs for non existing procedures. 1.2 Enhance existing procedure to improve detection of defects	Six Sigma Team/Done  Sherwin Gan/Done
7	<b>KPIV 8</b> Use of incorrect screws in PC stiffener (ELTESO PC) can induce probe damage.	a. Do one time check of all ELTESO PC if using standard screw.	1.1 Do one time check of all ELTESO PC if using standard screw. 1.2 Perform inspection using filler gauge.	Enan dela Cruz/ Done  Enan dela Cruz/ Done
8	<b>KPIV 9</b> Loading an incorrect / not updated BOP disk can smash the probe card and eventually cause probe damage.	a. Eliminate the use of BOP disk. Use prober to tester interface to set up the cleaning unit height per device requirement.	1.1 Eliminate the use of BOP disk. Use prober to tester interface to set up the cleaning unit height per device requirement.	Rod Salmorin, Sherwin Gan/Done

SW Test Workshop - June 5-8, 2016



# Corrective / Preventive Action (CAPA) Plan

Define

Measure

Analyze

Improve

Corrective / Preventive Action:

- DOE, and/or  
- Poka-Yoke

Implementation Result

Improve Phase Summary

Control



Item	Validated KPIV/Cause	Quick Win/s (Containment Action/s)	Permanent Action/s	Responsible/ Completion Date
9	<b>KPIV 10</b> Use of Sodium Hydroxide and old type epoxy (Duralco) can weaken the probe needle which can lead to premature needle misalignment .	<ul style="list-style-type: none"> <li>a. Implement gel pad during needle etching.</li> <li>b. Use of Pelnox epoxy</li> </ul>	<ul style="list-style-type: none"> <li>1.1 Implement gel pad during needle etching.</li> <li>1.2 Use of Pelnox epoxy (on high temp PC</li> <li>1.3 Implement touchcount monitoring on every probecard on high runner devices</li> </ul>	<p>Enan dela Cruz/ Done</p> <p>Enan dela Cruz/ As per rebuild./Done</p> <p>Enan dela Cruz/250k TD/Done</p>
10	<b>KPIV 11, 13</b> Use of worn out cleaning material and incorrect replacement of cleaning material can cause probe damage.	a. Used gel pad/lapping paper should be endorsed to line supervisor prior replacement of new one.	1.1 Used gel pad/lapping paper should be endorsed to line supervisor prior replacement of new one.	Vangie Ocampo / Done
11	<b>KPIV 12</b> Accumulated debris on the probe card needle causes probe damage.	a. Do online cleaning every middle of the lot for devices	1.1 Do online cleaning every middle of the lot for devices	Done

SW Test Workshop - June 5-8, 2016

# Corrective / Preventive Action (CAPA) Plan

Define

Measure

Analyze

Improve

Corrective / Preventive Action:

- DOE, and/or
- Poka-Yoke

Implementation Result

Improve Phase Summary

Control

Item	Validated KPIV/Cause	Quick Win/s (Containment Action/s)	Permanent Action/s	Responsible/ Completion Date
12	<b>KPIV 14</b> Leaning on test head and removal of cable on cable setup	a. Put warning sign "Do not lean on test head" for OH setup.	1.1 Put warning sign "Do not lean on test head" for OH setup.	Glenn Placido / Done
		b. Establish procedure for proper removal and installation of cables/PC on cable setup.	1.2 Establish procedure for proper removal and installation of cables/PC on cable setup.	Glenn Placido/ Done
			1.3 Vacuum Docking	Rod Salmorin – Done.
13	<b>KPIV 15</b> Probe Card Planarity	a. Establish procedure / criteria to detect probecard planarity issue during initial setup. Establish criteria.	1.1 . Establish procedure / criteria to detect probecard planarity issue during initial setup. Establish criteria.	Glenn Placido / Done.



SW Test Workshop - June 5-8, 2016



Define

Measure

Analyze

Improve

- Corrective / Preventive Action:
  - DOE, and/or
  - Poka-Yoke
- Implementation Result
- Improve Phase Summary


Control



## CAPA for Validated KPIV # 1

(Operational condition of the prober after equipment relocation)

Enhance equipment buy-off and use of bracket during transfer of prober.

Process	Before	After
Buy-off after prober transfer	Theta check using naked eye.	Theta check but with actual measurement of XY deviation.
Transfer of prober from one tester to another.	Does not use brackets during transfer of prober.	



Define

Measure

Analyze

Improve

- Corrective / Preventive Action:
  - DOE, and/or
  - Poka-Yoke
- Implementation Result
- Improve Phase Summary

Control



## CAPA for Validated KPIV # 2

(Operational condition of the prober using defective prober footings)

Enhance equipment buy-off and use of bracket during transfer of prober.

Process	Before	After
Transfer of prober from one tester to another.	No checking of prober footings condition.	Checking of prober footings prior equipment endorsement.

Define

Measure

Analyze

Improve

- Corrective / Preventive Action:
  - DOE, and/or
  - Poka-Yoke
- Implementation Result
- Improve Phase Summary

Control



## CAPA for Validated KPIV # 3,4,7

(Incorrect card relative z height and over drive; "Model not found" and "auto focus error" and Procedure is not yet robust/define)

Process	Before	After
Initial setup	Checking of probe mark is done visually.	Checking of probe mark is measured if within spec.
Ongoing probe.	No checking of theta.  Checking of probe marks after equipment intervention, start of shift is done using cross pattern.  No procedure define when encountered "Model not found" and "Auto-focus error".  Inspection every 6 <sup>th</sup> wafer is triggered manually.	Checking of theta.  Checking of probe marks after equipment intervention, start of shift is done using the last die that was used.  Define OCAP when encountered "Model not found" and "Auto-focus error".  Inspection every 6 <sup>th</sup> wafer is triggered by the interface.

Define

Measure

Analyze

Improve

□ Corrective / Preventive Action:

- DOE, and/or - Poka-Yoke

□ Implementation Result

□ Improve Phase Summary

Control



# CAPA for Validated KPIV # 3,4,7

(Incorrect card relative z height and over drive; "Model not found" and "auto focus error" and Procedure is not yet robust/define)

## THETA SHIFTING CHECKING PROCEDURE PRIOR PRODUCTION RUN:


Target Device: ALCA, HSBA, 19791

### Requirement, when to do?

- Operator to perform theta shifting checking every setup, new lot and next lot.
- For relocated Prober, Operator to indicate in the sort card that the prober to be used was newly relocated


### Step by step Procedure:

1. Perform Theta shifting check using fresh wafer before probe by inducing probemark on 4 pts (top to bottom, left to right)




2. Measure the theta XY shift, acceptable measurement should be  $(\approx / < 5\mu m)$
3. Record the value on the Sort setup sheet and coordinates of the dice.
4. Use the upper left corner bonding pad of the die as reference


Note: For OMAFA and OALCA use the smallest bond pad as reference  
: For Multi sites use the bonding pad of 1 site




5. At the Top of the wafer, position the Crosshair on Probe mark of upper left corner BP. When Done, Press Position display.



6. Go to INDEX mode and Index down the wafer to the Last Die at the bottom. Press "ZERO Reset"



7. Move the crosshair to its original position relative to the bonding pad.




8. X and Y position values on Prober screen should indicate your theta shifting. If any one of these values exceeds  $5\mu m$ , endorse the setup to Probe tech.
9. If these values are okay, then repeat step (5-8) for Bond pad of Left die to Right direction.

-END-

## NEW INLINE INSPECTION METHODOLOGY:

Inspection should be done after wafer probing, except for First wafer.

1. First wafer is considered setup wafer thus probe mark should be induced.
2. Perform inspection after every 6<sup>th</sup> wafer, last wafer, start of the shift and any intervention.
- Note: KLA pause before unloading is enabled**
3. For every 6<sup>th</sup> wafer and last wafer, inspect 5 dice cross pattern (top, mid bottom, left and right) using Probe mark template.
4. During inspection. Inspect also the bond pad periphery at high mag.



5. For every start of the shift, inspect 1 last die sorted. Take note of the coordinates and wafer number.
6. For any intervention inspect the 1<sup>st</sup> die sorted using the probe mark template. After equipment endorsement, inspect after 10th die sorted. Take note only of the 1<sup>st</sup> die sorted coordinate and the wafer number.

### Note: Interventions are:

- Change of peripherals (Probe card, Loadboard, cables)
- Change of overdrive
- Equipment repair (intervention by support group)
- Clearing of reference model if encountered "Model not found error".

## PC / Loadboard Installation on Cable Setup :

1. During setup Install probe card, Loadboard and cable prior performing needle alignment.
2. Any reseating done on the cable, needle alignment should be performed.

# SW Test Workshop - June 5-8, 2016



Define

Measure

Analyze

Improve

Corrective / Preventive Action:

- DOE, and/or  
- Poka-Yoke

Implementation Result

Improve Phase Summary

Control



# CAPA for Validated KPIV # 3,4,7

(Incorrect card relative z height and over drive; "Model not found" and "auto focus error" and Procedure is not yet robust/define)

ERROR MESSAGE	CAUSE OF ERROR	IMPACT TO PRODUCT	ERROR CATEGORY	RECOVERY	RESPONSIBLE
Prober Error: Load Cassette not set up	o Start was pressed but loader is not in loading position	Downtime	A	o Press "new cassette" (yellow button)	o Operator
Prober Error: Wafer ID not read (No ID characters)	o Uncalibrated OCR o Wafer scribe not readable o Different format of wafer scribe	Misprocessing (Wrong wafer)	C	o Call Maintenance if wafer scribe is readable or in correct format otherwise call process/TA o Calibrate OCR o (Fab feedback) if wafer scribe is unreadable/in different wafer scribe format.	o Operator o Maintenance o Process /TA
Prober Error: Needle alignment error (Needle position not found. Low Mag)	Inconsistent position of PC	o Offset probing due to wrong site assignment for multi-site. o Single site - shifted probemark. o Possible probedamage	C	Perform Manual alignment	o Operator
Prober Error: Needle alignment error (Insufficient number of Needles found. High Mag)	o PC with planarity issue o Smash probecard o Wrong site assignment	o Offset probing due to wrong site assignment for multi-site. o Shifted probemark for single site. o Possible probedamage	C	o Check if there is a matched needle vs prober reference. If none, call technician. o Check is there is probecard planarity issue. o Replace probecard	o Operator o Maintenance
Error: Tester Command: EITst:loadprogram error (1).	o Loadstring not define at KLA.	Possible wrong test program	C	o Endorse to TSA. o Check headstage/Sidepanel if open. o Call tech.	o Operator o Operator
Prober Error: Head stage open	o Unlock head stage	Safety.	C	o Check interlock	o Technician
Prober Error: Needle alignment error (Low mag. search position shifted)	Inconsistent position of PC	o Offset probing due to wrong site assignment for multi-site. o Shifted probemark for single site. o Possible probedamage	C	Manual alignment.	o Operator
Prober Error: Model not found	Theta of PC is out of spec	o Offset probing o Probe damage	C	o Change reference model o If problem cannot be corrected, Endorse to tech o Replace PC	o Operator o Technician
Prober Error: Focus point not found within processing area	Blurred image : possible cause : - unplanarize check - profile sensor not calibrated	Downtime	A	o Endorse to tech o Calibrate profile sensor o Planarize chuck o Hard down	o Operator o Technician
Prober Error: GPIB receive command format invalid	Corrupted KLA file	Downtime	A	o Re-initialize prober o Reload KLA o Reload BOP o Endorse to TA	o Operator
Prober Error: Elevator 1 (Wafer safe sensor)	o Protruding wafer on the cassette. o Equipment Vibration	Broken wafer	B	Endorse to technician.	o Operator

SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze

Improve

□ Corrective / Preventive Action:

- DOE, and/or  
- Poka-Yoke

□ Implementation Result

□ Improve Phase Summary

Control



## CAPA for Validated KPIV # 3,4,7

(Incorrect card relative z height and over drive; "Model not found" and "auto focus error" and Procedure is not yet robust/define)

File Tools Data Directories

NFC Navigator Plus

Edit Setup Main Cell Status Single Wafer Mapping Composite Wafer Mapping System Configuration Privileges: Operator

Select Setup... QMORF001UF1A Default Setup: APH90... Reload Default Edit Control Map File Close

Type: Standalone

Setup File Sections	PASS 1 - GENERAL
◇ WAFER TYPE DESCRIPTION	ENABLE APP SUB-PASS? NO
◇ XML OUTPUT	STOP BEFORE UNLOADING? YES
◇ OCR USAGE	SAVE MAP AT STOP? NO
◇ REFERENCE DIE DATA SETTINGS	STOP AT EVERY? ___ (wafer) 6
◇ PINS-DOWN Z HEIGHT ADJUSTMENT	ALARM AT STOP? YES
◇ FREE INDEX	STOP AT FIRST DIE? YES
◇ BINCODE ASSIGNMENTS	STOP AT FIRST DIE TIMEOUT [-1,0-600] sec 0
◇ BIN CODE TEXT	STOP AT EVERY? ___ (wafer) 99
◇ INKING OPTIONS	ALARM AT STOP? NO
◇ PASS 1 - GENERAL	ENABLE PAUSE BEFORE TESTING DIE? NO
◇ - Subpass Control Maps	
◇ PASS 1 - PROBECARD	
◇ PASS 1 - YIELD/PROCESS PARAMETERS	
◇ - Total Result Monitors	
◇ - Site Result Monitors	
◇ - Total Test Data Monitors	
◇ - Site Test Data Monitors	
◇ PASS 2 - GENERAL	

SW Test Workshop - June 5-8, 2016



Define

Measure

Analyze

Improve

- Corrective / Preventive Action:
  - DOE, and/or
  - Poka-Yoke

- Implementation Result
- Improve Phase Summary

Control



# CAPA for Validated KPIV # 5,6

(Incorrect soak time have effect on probe mark size and position.)

Process	Before	After
Soaking before : <ul style="list-style-type: none"><li>• Probing</li><li>• Any intervention</li></ul>	Manual soaking	Auto-soaking. Integrated to KLA.

The screenshot shows the INVANTE software interface for setting up a probe card. The 'PASS 2 - PROBE CARD' section is active. A red box highlights the 'Hot Chuck Soak Time? (seconds)' parameter, which is set to 120. Other parameters include 'Needle Align. Interval at Chip Unit? (0-60min)' set to 0, 'Needle Align. End Time at Chip Unit? (0-1440)' set to 0, 'Chuck Height Revise Function?' set to YES, 'Wait Time Start Meas. Chuck Height (0-99min)' set to 5, 'Interval of Meas. of Chuck Height (0-99min)' set to 5, 'Watch Time of Meas. of Chuck Height (0-99min)' set to 60, 'Recovery At Alignment Stop' set to Alarm Stop, 'Perform Auto Focusing' set to Yes, 'Hot Chuck Soak X,Y location?' set to 18 and 13, and 'Hot Chuck Pause/Continue Soak Time? (seconds)' set to 0.

SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze

Improve

- Corrective / Preventive Action:
  - DOE, and/or
  - Poka-Yoke
- Implementation Result
- Improve Phase Summary



Control



## CAPA for Validated KPIV # 8

(Use of incorrect screws in PC stiffener (ELTESO PC) )

Process	Before	After
Probe Card Build	Use of non-standard screws on ELTESO probe card is ok.	Non-standard screws are replaced with the POR screws.  Perform inspection using filler gauge.



SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze

Improve

□ Corrective / Preventive Action:

- DOE, and/or  
- Poka-Yoke

□ Implementation Result

□ Improve Phase Summary

Control



## CAPA for Validated KPIV # 9

(Loading an incorrect / not updated BOP disk can smash the probe card)

Process	Before	After
Needle Cleaning	Use of BOP disk per cleaning material.	Include needle cleaning info on the device KLA.

File Tools Data Directories Help

NFC Navigator Plus INVANTEST

Edit Setup Main Cell Status Single Wafer Mapping Composite Wafer Mapping System Configuration Privileges: Operator

Select Setup... DHSBR004GF1A Default Setup: APH90. Reload Default Edit Control Map File Close

Type: Standalone

Setup File Sections

- ◆ OCR USAGE
- ◆ REFERENCE DIE DATA SETTINGS
- ◆ PINS-DOWN Z HEIGHT ADJUSTMENT
- ◆ FREE INDEX
- ◆ BINCODE ASSIGNMENTS
- ◆ BIN CODE TEXT
- ◆ INKING OPTIONS
- ◆ PASS 1 - GENERAL
  - ◆ - Subpass Control Maps
- ◆ **PASS 1 - PROBE CARD**
- ◆ PASS 1 - YIELD/PROCESS PARAMETERS
  - ◆ - Total Result Monitors
  - ◆ - Site Result Monitors
  - ◆ - Total Test Data Monitors
  - ◆ - Site Test Data Monitors
- ◆ PASS 2 - GENERAL
- ◆ PASS 2 - PROBE CARD
- ◆ PASS 2 - YIELD/PROCESS PARAMETERS

PASS 1 - PROBE CARD

RETEST ALL SITES (MULTI-DIE ONLY?) NO

USE PROBE NEEDLE POLISH? YES

CLEANING UNIT? [1332] STANDARD-PAD

CLEANING UNIT HEIGHT (um) 370

CLEANING OVERDRIVE (um) 80

SHIFT BETWEEN TOUCHDOWNS (um) 60

POLISH PROBES AFTER? \_\_\_\_ (dice) 220

POLISH PROBES AFTER? \_\_\_\_ (wafers) 1

POLISH NEEDLE WHEN STARTING LOT? NO

POLISH NEEDLE AFTER LAST WAFER? NO

PERFORM BRUSH NEEDLE CLEANING? NO

SW Test Workshop - June 5-8, 2016



Define

Measure

Analyze

Improve

- Corrective / Preventive Action:
  - DOE, and/or
  - Poka-Yoke
- Implementation Result
- Improve Phase Summary

Control



# CAPA for Validated KPIV # 11,13

(Use of worn out cleaning material and incorrect replacement of cleaning material.)

Process	Before	After
Needle Cleaning	No procedure on replacement of cleaning material.	Established procedure that ensures replacement of cleaning material.

### Cleaning Pad Monitoring Logsheet

Tester: _____	Tester: _____	Tester: _____	Tester: _____
Prober: _____	Prober: _____	Prober: _____	Prober: _____
Date: _____	Date: _____	Date: _____	Date: _____
Time: _____	Time: _____	Time: _____	Time: _____
Operator: _____	Operator: _____	Operator: _____	Operator: _____

Define

Measure

Analyze

Improve

- Corrective / Preventive Action:
  - DOE, and/or
  - Poka-Yoke
- Implementation Result
- Improve Phase Summary

Control



# CAPA for Validated KPIV # 12

(Accumulated debris on the probe card needle.)

Process	Before	After
Probing	No procedure on how to prevent accumulation of debris on probe card needle.	Online needle cleaning of probe card needle after 12 <sup>th</sup> wafer.

## SORT SETUP SHEET

New Device



DEVICE : 19791-001  
RC : L  
DOD Y/N? : N  
PART TITLE : RUBY  
PH : MS-SIAS-AUT-MS  
PART TYPE : DWR  
CUSTOMER : NAGANO KEIKI CO LTD

### SPECIAL INSTRUCTIONS

\*\*\* Sort Requirements \*\*\*

Use Red Amp cables.

### LOADBOARD:

WS1 ---> 19791-001-61-0A-0000-01  
WS2 ---> 19791-001-61-0A-0000-00

" Do not use production wafers for setup troubleshooting. Only reference wafer should be used."

New probe card should be using the new probe card drawing .

### Special Instruction for WS1 and WS2 Setup

Online cleaning of probecard by PC personnel is required every start and mid-wafer of the lot; stop probing and call the attention of PC personnel (MT to request to PC personnel to note at sort card the wafer ID of current wafer after online cleaning)

Define

Measure

Analyze

Improve

- Corrective / Preventive Action:
  - DOE, and/or
  - Poka-Yoke
- Implementation Result
- Improve Phase Summary


Control



# CAPA for Validated KPIV # 14

(Leaning on test head and removal of cable on cable setup.)

Process	Before	After
Probing	Procedure is not clear when reseating cable on a cable set-up.	Established procedure to perform needle alignment every reseating of cable.  Put a warning sign not to lead on test head on OH set-up.



SW Test Workshop - June 5-8, 2016



Define

Measure

Analyze

Improve

□ Corrective / Preventive Action:

- DOE, and/or  
- Poka-Yoke


□ Implementation Result

□ Improve Phase Summary

Control



## Before and After Implementation Comparison



SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze

Improve

Corrective / Preventive Action:

- DOE, and/or  
- Poka-Yoke

Implementation Result


Improve Phase Summary

Control

# Before and After Implementation Comparison

## Secondary Metric

### Probe Damage MRB Trend



MRB occurrence due to probe damage was reduced from 16 occurrence per month to 2 occurrence per month



SW Test Workshop - June 5-8, 2016

# SIX SIGMA

## The DMAIC Model



Define Opportunity  
*(What is important?)*



Measure Performance  
*(How are we doing?)*



Analyze Opportunity  
*(What is wrong?)*



Improve Performance  
*(What needs to be done?)*



Control Performance  
*(How do we guarantee performance?)*

**Define** the goals of the improvement activity.

Select the appropriate responses (Y's) to be improved.

**Measure** the existing system.

Gather data to measure and verify the response variable --- the problem or improvement opportunity.

**Analyze** the system to identify the causes or gaps.

Find the relevant X's.

**Improve** the system.

Identify ways to eliminate the gap.

Reduce variability or eliminate the cause.

**Control** the new system.

With the desired improvements in place, monitor the process to sustain the improvements.

SW Test Workshop - June 5-8, 2016



# Control

- Standardization

1.0 Operating Procedure Specification – OK

2.0 Work Instruction – OK

3.0 FMEA – OK

4.0 Control Plan – OK

Define Measure Analyze Improve



SW Test Workshop - June 5-8, 2016

# Standardization Plan

Define

Measure

Analyze

Improve

Control

- Standardization/Documentation/Fan-Out
- Project Transition Plan
- Financial Validation
- Control Phase Summary
- Key Learning



Item	Action Item	Due Date	Resp.	Remarks
1	Standardization of prober to tester interface enabled pause before unloading as per defined inspection scheme per tester.	Start: Ww20	Glenn Placido	Done and Implemented
2	Standardization of actual wafer probe mark location by using probe mark template.	W20	Jonah Capua	Done and Implemented.
3	Generation of efficient set-up procedure for an early detection of equipment/probe card problem prior full lot probing.	W18	Glenn Placido	Done

SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze

Improve

Control

- Standardization/Documentation/Fan-Out
- Project Transition Plan
- Financial Validation
- Control Phase Summary
- Key Learning




# Procedure / Work Instruction

From: **None**


To:

<b>ON Semiconductor</b> Probe Standard Operating Procedure	Document Number 201065	Revision AG
Page 27 of 71		


2.9.3.4 Use the upper left corner bonding pad of the die as reference  
 Note : For 0MAFA and DALCA use the smallest bond pad as reference  
 : For Multi sites use the bonding of 1 site




2.9.3.5 At the Top of the wafer, position the Crosshair on Probe mark of upper left corner BP. When Done, Press Position display.



2.9.3.6 Go to INDEX mode and Index down the wafer to the Last Die at the bottom. Press "ZERO Reset"



2.9.3.7 X and Y position values should indicate your Probe mark shifting  
 2.9.3.8 If any one of these values exceeds 4um, endorse the setup to Probe tech.  
 2.9.3.9 Move the crosshair to its original position relative to the bonding pad.



2.9.3.10 If these values are okay, then repeat step (5-8) for Bond pad of Left die to Right direction

2.9.4 Offline Probe mark inspection using microscope with autoloader and image capturing system. Refer to Appendix 1 for Autoloader Operation Procedure.

2.9.5 Offline Probe mark inspection using microscope only without autoloader

2.9.5.1 Press the switch in front of the microscope base to turn on the lamp.



Define

Measure

Analyze

Improve

Control

- Standardization/Documentation/Fan-Out
- Project Transition Plan
- Financial Validation
- Control Phase Summary
- Key Learning



# Probe FMEA

From: **None**

To:

Design/Process Function/Requirement	Potential Failure Mode	Potential Effect(s) of Failure	SEV	Occurrence	Potential Cause(s)/Mechanism	Current Design/Process Prevention Controls	OC	Current Design/Process Detection Controls	DET	RPN	Recommended Action(s)	Responsibility & Target Completion Date	Action Taken & Effective Date	SEV	Occurrence	DET	RPN
	probe damage	Low yield/wafer scrap, Reliability issue in electrical test (device degrading)/EFAR	T		Probe mark on the exclusion zone	Set edge exclusion zone on control map, 3mm for 5" wafer, 4mm for 6" or 8" wafer	5	Visual inspection	T	245	DMAIC	Glenn Placido	03*2012				
			T		Probe cord not soaked at set-up (if > 25°C)	Check revise is set on Prober Basic Operating Parameter Needle soaking procedure for ELTESO (> 125C)	2	Visual inspection	T	36	Include soaking as part of KLA parameter	Glenn Placido	03*2012				
			T		Probe cord expansion issue due to unstandardize screws	Use of filler gauge to check distance on elteso P.C	2	Visual inspection	T	36	Use only PDR screws on elteso PC	Ense Dela Cruz	Done				
			T		Incorrect cleaning parameter due to wrong BOP disk use	BOP Disk with proper label	2	Visual inspection	T	36	Include cleaning unit parameter on KLA as per device specific	Glenn Placido	04*2				
			T		Leaning on test head during probing	None	3	Visual inspection	6	168	Put Warning sign "DO NOT LEAN ON TEST HEAD DURING PROBING".	Glenn Placido	done				
			T		Prober shifting due to prober transport from other tester	Equipment by-off	3	Visual inspection	7	147	Use of XY bracket	Rod Salmorin	Done				
										147	Checking of prober footing	Rod Salmorin	Done				

SW Test Workshop - June 5-8, 2016

Define

Measure

Analyze

Improve

Control

- Standardization/ Documentation/ Fan-Out
- Project Transition Plan
- Financial Validation
- Control Phase Summary
- Key Learning



# Training Plan

### THETA SHIFTING CHECKING PROCEDURE PRIOR PRODUCTION RUN:

Operator to perform theta shifting checking every setup, new lot and next lot.

- Perform Theta shifting check using fresh water before probe by inducing probe mark on 4 pts. (top to bottom, left to right)

- Measure the theta XY shift, acceptable measurement should be (N/C 5um).
- Record the value on the Sort setup sheet and coordinates of the dice.
- Use the upper left corner bonding pad of the die as reference

Note: for OMAFA and SALCA use the smallest bond pad as reference and For Multi sites use the bonding pad of 1 site

- At the Top of the wafer, position the Crosshair on Probe mark of upper left corner BP. When Done, Press Position display

- Go to INDEX mode and index down the wafer to the Last Die at the bottom. Press "ZERO Reset"

- Move the crosshair to its original position relative to the bonding pad

- X and Y position values on Prober screen should indicate your theta shifting, if any one of these values exceeds 5um, endorse the setup to Probe tech.
- If these values are okay, then repeat step (3-6) for Bond pad of Left die to Right direction

### NEW INLINE INSPECTION METHODOLOGY:

Inspection should be done after water probing, except for First wafer.

- First wafer is considered setup wafer thus probe mark should be induced
- Perform inspection after every 6<sup>th</sup> wafer, last wafer, start of the shift and any intervention

Note: KLA pause before unloading is enable

- For every 6<sup>th</sup> wafer and last wafer, inspect 5 dice cross pattern (top, mid bottom, left and right) using Probe mark template
- During inspection, inspect also the bond pad periphery at high mag

- For every start of the shift, inspect 1 last die sorted. Take note of the coordinates and wafer number
- For any intervention inspect the 1<sup>st</sup> die sorted using the probe mark template. After equipment endorsement, inspect after 10th die sorted. Take note only of the 1<sup>st</sup> die sorted coordinate and the wafer number.

Note: Interventions are:

- Change of peripherals (Probe card, Loadboard, cables)
- Change of overdrive
- Equipment repair (intervention by support group)
- Clearing of reference model if encountered "Model not found error".

### SCRIBE FORMAT

VALID SCRIBE FORMAT:

Where:

- A = alpha characters
- N = numeric characters
- CS = string checksum.

FAB2: AAANNNN-NN-CS or A'NNNNN-NN-CS

FAB10: ANNNNN-NN-CS

Gresham: NNAANNNAACS

TSMC: ANANNN-NNCS or AN'NNN-NNCS

Magnachip: AAANNNN-NNCS

Note on CS:

- CS represents 2 characters: 1<sup>st</sup> is an alpha character (from A-H) and the 2<sup>nd</sup> is a numeric character (from 0-7)
- It is important to enter the last 2 characters as 'CS', these are the checksum value of the string which is being computed by the OCR software.

Please DO NOT edit CONFIG 0 to 5, these are allotted for the following FABs


Config 0 and 1 -	Fab2	6"
Config 2 and 3 -	Fab10	8"
Config 4 and 5 -	Greshm	8"

Use config 6 and above for the 1f conditions

- If there's a need to reconfigure the above settings
- Needed for another external FAB devices


Pls refer to 211021 for OCR updating Procedure

- End of 2014 shows increase in MRB occurrence






- Start of 2015 shows increase in probe damage scraps and incidence



- Probe damage are defects induce during probing.



Example of a good probe mark




- Probe mark is center
- Not touching the sealant

Common Probe damage defect during 6 sigma



## What If??

- Probe marks are centered but there are disturbance on the seal ring?



New defect signature not included during PD six sigma project



# EDX Analysis showed probe damage reaching the die specifically the bond ring.

## Analysis: FA report of worst pad with damage 0WICA-002-DWR NE39112.1 SEM and EDX Results

**Summary Narrative:** One die (SN2 13,1) with noted probe damaged on the bond pads was submitted for analysis, to determine if the probe damage reaches the die. Optical inspection after polyimide removal showed probe damage reaching the die specifically the bond pad ring.




Figure 1. Sample 1.




Figure 2: Location of the affected pads.

## Analysis: FA report

0WICA-002-DWR NE39112.1 SEM and EDX Results




Figure 3: Bond Pad A




Figure 4: Bond Pad A




Figure 5: SEM image of Pad A





Figure 6: 8000x magnification

# Our Findings?

- During probing, the leg of the needle touches and damages the highest part of the bond pad which is the sealant with polyimide layer. The needle impression came from the heel of the needle and not the full diameter of the needle.
- This explains the gap between the probe marks and the damage sealant.
- This is most rampant on the 3x3mils bond pad due to the limitation on the bond pad area.






## Quick Wins:

- Perform tighter PCB scrub analysis on PRVx
- Tighten probe needle diameter requirement to 0.8mil to 1mil vs 0.8mil to 1.2mils.
- Convert probe needle type from Cantilever to Vertical.




Result:



SW Test Workshop - June 5-8, 2016

# What Went Wrong?

- ❑ 2 KPIVs under FMEA was deprioritized and missed out.



1. No define procedure during reprobe.
2. Bond pad size to probe needle limitation



Define

Measure

Analyze

Improve

Control

- Standardization/  
Documentation/  
Fan-Out
- Project Transition  
Plan
- Financial  
Validation
- Control Phase  
Summary
- Key Learning



## Key Learning

1. Strong sponsorship by the top management
2. Strong team leadership and teamwork
3. Correct ownership of the problem
4. Use of correct performance metric measurements
5. Thoroughness in process risk analysis
6. Correct use of the appropriate statistical and problem-solving tools
7. Emphasis on poka-yoke solutions
8. Proper documentation
9. Proper fan-out
10. Follow through of improvement actions through process audit
11. Continuous monitoring of a DMAIC project.
  - New learnings and findings along the way
12. Revisit low KPIVs.
  - This might harm you in the future.

**SW Test Workshop - June 5-8, 2016**



End

Thank You!

SW Test Workshop - June 5-8, 2016